

**Operator: BONANZA CREEK ENERGY OPERATING  
COMPANY**

**Location Name: PRONGHORN-65N61W 12NWNW**

**Loc ID: 306049**

**Inspection: 718700171**

**CA:** This location does not comply with Rule 1004. During this inspection, it was observed that the former access road/location entrance does not appear to have been recontoured or graded with evidence of road base material. Additionally, there was an opening/subsidence west of the location entrance which was immediately reported to Operator representative (Eli C.) on 03/05/2025. The majority of the location appears to be progressing with desirable native vegetation observed throughout. Refer to attached inspection photos. Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

**CA Resolution:** Operator has addressed the issues in order to comply with Rule 1004.

**CA:** This location does not comply with Rule 1002.f. During this inspection, erosion degradation was observed at the former location entrance/access road, which does not appear to have been reclaimed.

**CA Resolution:** Operator has addressed the issues in order to comply with Rule 1002.f.