

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/11/2025

Submitted Date:

03/20/2025

Document Number:

711902144

FIELD INSPECTION FORM

Loc ID: 316940 Inspector Name: SCHURE, KYM On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 31257
Name of Operator: FRITZLER RESOURCES INC
Address: P O BOX 114
City: FORT MORGAN State: CO Zip: 80701

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@state.co.us	
Quint, Craig		craig.quint@state.co.us	
,		gfritzler@bresnan.net	
Heibel, Krystal		krystal.heibel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
233352	WELL	PR	10/01/2021	OW	121-05388	BEN 1	PR

General Comment:

REVIEW OF FIR DOC#711902124 OMITTED CA'S WITH DATES AND CONTACT FOR PW PIT#2 INADEQUATE FREEBOARD. THIS CA ISSUE IS CITED WITHIN THIS FIR.

CONTACT ECMC ENVIRONMENTAL GROUP FOR DIRECTIVES

SEE LOCATION PHOTOGRAPHS FOR REFERENCE

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate
Comment: INADEQUATE FREEBOARD ON PW PIT #2 ON SOUTH END OF PW PIT SEE PHOTOGRAPHS ATTACHED				
Corrective Action: LOWER FLUID LEVEL SO AT LEAST (2) FEET OF FREEBOARD EXISTS PER RULE 909.f. (48) hrs. to repair Reconstruct/repair berm on south end of PW pit. CONTACT ECMC ENVIRONMENTAL GROUP FOR FURTHER DIRECTIVES				Date: <u>03/22/2025</u>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 233352 Type: WELL API Number: 121-05388 Status: PR Insp. Status: PR

Producing Well

Comment: CA'S CITED WITHIN THIS FIR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
PLEASE READ FIR COMPLETELY AND PERFORM CA'S WITH DATES CITED WITHIN THIS FIR. CONTACT ECMC ENVIRONMENTAL GROUP FOR DIRECTIVES AND FOLLOW-UP INSPECTION FOR ENVIRONMENTAL ISSUES. NOTIFY NE FIELD INSPECTOR ON ALL OTHER CA'S PERFORMANCE COMPLETION	schureky	03/20/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404136085	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6968133
711902145	LOCATION PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6968127