

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/17/2025

Submitted Date:

03/20/2025

Document Number:

718100318**FIELD INSPECTION FORM**Loc ID 426478 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426478	LOCATION	AC			-	SG L24 496	RI

General Comment:

On 3/17/2025, Western Reclamation Work Lead Trujillo conducted an interim reclamation and stormwater inspection at Caerus Piceance LLC's ELU SG/L24 496 location in Garfield County, Colorado.

Location is Fee Surface / Fee Mineral

Location is within the following High Priority Habitats: Elk Production Area; Mule Deer Migration Corridor; Greater Sage Grouse Priority Habitat Management Area; Mule Deer Migration Corridor

The following compliance issues were observed during this inspection:

- Wildlife Protections
- Good Housekeeping
- Rat, mouse or bore hole not closed/backfilled

Refer to the Location, Reclamation and Stormwater sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Signage at tank battery not posted pursuant to 605.e		
Corrective Action:	Comly with Rule 605.e	Date:	04/20/2025
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels posted on the back end of the tank; this is not conspicuous placement.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-866-580-9382 / 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Various trash/debris observed at and around the methanol tank on the east end of the Location.		
Corrective Action:	Comply with 606 rules.	Date:	03/16/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Other	#		corrective date
Comment:	Porta-john on SW end of Location has been physically secured.		
Corrective Action:		Date:	
Type: Other	#		
Comment:	Open pipe observed within the string of wells. BMPs to prevent wildlife access to the pipe are missing or insufficient.		
Corrective Action:	Install or repair wildlife protection equipment.	Date:	03/30/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,

Comment:					
Corrective Action:					Date: <input type="text"/>
Paint					
Condition	<input type="text"/>	<input type="text"/>			
Other (Content)	<input type="text"/>				<input type="text"/>
Other (Capacity)	210 BBL				<input type="text"/>
Other (Type)	<input type="text"/>				<input type="text"/>
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	<input type="text"/>	<input type="text"/>	<input type="text"/>	Adequate	<input type="text"/>
Comment:	Containment measure appeared to be in proper functioning condition at time of inspection.				
Corrective Action:					Date: <input type="text"/>
Venting:					
Yes/No	<input type="text"/>			<input type="text"/>	<input type="text"/>
Comment:	<input type="text"/>			<input type="text"/>	<input type="text"/>
Corrective Action:	<input type="text"/>			Date:	<input type="text"/>
Flaring:					
Type	<input type="text"/>			<input type="text"/>	
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>			Date:	<input type="text"/>

Inspected Facilities									
Facility ID:	426478	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____ I _____

Comment Limited inspection due to snow cover. Inspection #696205114 observed Noxious weeds (Musk thistle) within interim areas of the Location. Operator submitted Resolution 403502233 stating weeds were treated/removed.

Noxious weeds not apparent at time of inspection. This CA is being considered resolved, though it is noted ongoing weed monitoring/management is required until Location receives a passing final reclamation inspection.

It was observed in this inspection that a rat or other bore hole next to well API 045-21166 has not been closed/backfilled pursuant to Rule 1003.a.

Corrective Action **Comply with Rule 1003.a**

Date **04/20/2025**

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action: Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404136410	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6968387
718100323	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6968381