

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/13/2025

Submitted Date:

03/20/2025

Document Number:

698603325

**FIELD INSPECTION FORM**

Loc ID 303547 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE State: CO Zip: 80424

**Findings:**

- 18 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253268	WELL	PR	09/18/1986	GW	125-07145	BROPHY, T 50-31	PR

**General Comment:**

Routine Inspection. On 3/13/2025 Inspector arrived at well location to complete routine well location inspection. Upon arrival Inspector discovered active release at wellhead. Produced water was leaking from the check valve located on wellhead tree water line. Notified OWN Resources Field Forman via text message at 3:54 PM. Based on conditions at the well spill is estimated to be less than one barrel.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign at wellhead location.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Lease sign posted at remote Gas Meter Run.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact information posted on Lease sign.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Produced Water	WELLHEAD	<= 1 bbl	
Comment:	Active release at wellhead. Produced water was leaking from the check valve located on wellhead tree water line. Based on conditions at the well spill is estimated to be less than one barrel		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.  Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil.		Date: <u>04/20/2025</u>
In Containment: No			
Comment:	Reported to OWN Resources Operating LLC Field Foremen 3/13/2025 via text message at 3:54 PM.		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Stock panel fencing around surface equipment at remote gas metering location.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Prime Mover	# 0		corrective date
Comment:	Electric Drive Motor removed at time of inspection.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		

Comment:	Pump Jack Power and Control Panel.	Date:	
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:	Dehydrator (Drip Bottle) on gas meter run inlet.	Date:	
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located on CR 49 & CR P at shared gathering location. Digital Gas Meter Run. Meter Calibration/Test Log dated 3-3-23. Well Inlet Valve open. Gas Outlet Valve open. Meter not calibrated annually.	Date:	
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	04/20/2025
Type: Vertical Separator	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.	Date:	
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Shared Remote Gas Meter Shed.	Date:	
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve closed. Casing valve open.  Active release at wellhead. Produced water was leaking from the check valve located on wellhead tree water line.	Date:	
Corrective Action:	Operators will promptly investigate, and if appropriate, repair, replace, or remediate any malfunctioning equipment or process. Comply with Rule 609.a.  15 days. If leak is found Immediate call to operator 24 hours to fix the leak or isolate leak.	Date:	03/14/2025
Type: Pump Jack	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Remote Separator Shed.	Date:	
Corrective Action:		Date:	

**Venting:**

Yes/No	NO	Date:	
Comment:		Date:	
Corrective Action:		Date:	

**Flaring:**

Type		Date:	
Comment:		Date:	
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 253268 Type: WELL API Number: 125-07145 Status: PR Insp. Status: PR

**Producing Well**

Comment: Rods and tubing in wellbore. Tubing valve closed. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.  
Electronic Well File reflects last Production/Status reported 1/1/2025 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404136528	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6968595">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6968595</a>
698603356	Inspection photos.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6968587">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6968587</a>