

Inspection Photos

API: 055-06316

Operator: OXY USA INC

Inspection Date: 3/26/2025

County: HUERFANO



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the access road. The rock check dams shown at red arrow are filled in with sediment and require maintenance.



Inspection Photos



Photo 2. Facing back northwest along the access road. Theis check dam is in needof maintenance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing southeast as the access road ascends to the location. There are insufficient BMP's to prevent erosion. Previous CA was not completed.



Inspection Photos



Photo 4. Facing back north the steep grade of access road. Stormwater is not being diverted off the road which is causing erosion of the road. Stormwater should be divert toward red arrow and into a sediment trap. A water bar would also help direct stormwater off the road.



Inspection Photos



Photo 5. Facing southwest toward the wellsite.

