

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2025

Submitted Date:

03/21/2025

Document Number:

710100375**FIELD INSPECTION FORM**Loc ID 489507 Inspector Name: Anderson, Laurel On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kiel, Macy	970-515-1110	Macy_Kiel@oxy.com	Staff Environmental Engineer
,		ECMCInspections@Oxy.com	All Inspections
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental

General Comment:

ECMC Environmental Inspection of the following Kerr McGee/Oxy (Operator) facilities:
 Di Paolo Red W 25-9,10 & 9XJI Tank Battery
 Facility ID 489508
 Location ID 489507

Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no Operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Current site status:

- Weeds/debris/trash/unused equipment
- Inadequate secondary containment berms (burrows/walls removed)
- ASTs rusted/peeling paint

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	Weeds, unused equipment, trash and debris observed throughout the tank battery (See Photos). Lack of maintenance/good housekeeping.		
Corrective Action:	Comply with Rules 606 and 1002.f.(2).D.		Date: 04/04/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	OTHER	STEEL AST		,	
Comment:	Two 210-bbl steel crude oil ASTs. Paint is worn and tanks are starting to rust.					
Corrective Action:					Date:	

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Inadequate secondary containment. Animal burrows and weeds were observed in the shared produced water vessel/crude oil AST earthen secondary containment berm (See Photos). The horizontal separator earthen secondary containment berm appears to have been reworked and does not appear to be adequately compacted. (See Photos).			
Corrective Action:	Comply with Rules 902.a., 902.b. and 902.c. Operators shall maintain earthen secondary containment berms to prevent pollution, adverse environmental impacts and the potential for unauthorized discharge of oil, condensate, gas, and/or other E&P Waste.			Date: 04/04/2025

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404137333	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6969570
710100376	2025_0306_ DI PAOLO RED W 25-10_Photo Documentation	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6969560