

Final Reclamation and Stormwater Inspection

March 25, 2025

Operator: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 320128

Well Name: ANDERSON #5

Inspection Document #: 718600437

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ANDERSON #5
Location ID: 320128



Photo 1. Looking south down the former access road. Oil and gas equipment has been removed. The northern portion of access road is primarily list C noxious weed Downy Brome. Some desirable vegetation is beginning to establish on the access road.



Photo 2. Access road near the well location looking north. An area with less vegetation than surrounding area. Desirable vegetation appears to be progressing towards 80% coverage.



Inspection Photos
Location Name: ANDERSON #5
Location ID: 320128



Photo 3. Looking west across the wellsite. Well location has some bare spots and predominantly downy brome. There is some desirable vegetation present on location.



Photo 4. Looking north across location. No oil and gas equipment remains. Bare spot visible.



Inspection Photos
Location Name: ANDERSON #5
Location ID: 320128



Photo 5. Looking northwest across wellbore. Primarily Downy Brome. Undesirable weed Kochia is present on location. Some desirable vegetation has established on location.



Photo 6. Looking northeast down two track towards flowline joint/ spill #445184. Desirable vegetation appears to be progressing on two track.



Inspection Photos
Location Name: ANDERSON #5
Location ID: 320128



Photo 7. Reference vegetation to the east of well location.