

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/26/2025

Submitted Date:

03/31/2025

Document Number:

708303632

FIELD INSPECTION FORM

Loc ID: 335497
Inspector Name: Morris, Matthew
On-Site Inspection:
2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED
Findings:
 6 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Smelser, Wayne		wayne.smelser@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294537	WELL	PR	08/14/2008	GW	045-15514	SPECIALTY 34B-21-692	PR
294538	WELL	PR	08/09/2008	GW	045-15513	SPECIALTY 44B-21-692	PR
294664	WELL	PR	08/15/2008	GW	045-15563	SPECIALTY 33B-21-692	PR
294665	WELL	PR	08/14/2008	GW	045-15564	SPECIALTY 33D-21-692	PR
294666	WELL	PR	08/12/2008	GW	045-15565	SPECIALTY 34D-21-692	PR
294667	WELL	PR	08/16/2008	GW	045-15566	SPECIALTY 43B-21-692	PR
294668	WELL	PR	08/09/2008	GW	045-15567	SPECIALTY 43D-21-692	PR
294669	WELL	PR	08/14/2008	GW	045-15568	SPECIALTY 44D-21-692	PR

General Comment:
[CECMC Audit Report Summary](#)
 On 3/26/2025 at approximately 13:35, Compliance Inspector Matthew Morris conducted an on-site audit at TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/21SWSE at Location ID #335497 in Garfield County, Colorado.
 During the audit, the following compliance issues were observed:
 1) Illegible wellhead signs
 A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
 This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Multiple illegible wellhead signs.		
Corrective Action:	Install signs to comply with Rule 605.d.	Date:	05/01/2025

Emergency Contact Number:

Comment:	911/(970)285-9377		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	

Equipment:

Type		#		corrective date
Bradenhead		8		
Comment:				
Corrective Action:			Date:	
Plunger Lift		8		
Comment:				
Corrective Action:			Date:	
Ancillary equipment		1		
Comment:	Chemical tank			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	294537	Type:	WELL	API Number:	045-15514	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	294538	Type:	WELL	API Number:	045-15513	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	294664	Type:	WELL	API Number:	045-15563	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	294665	Type:	WELL	API Number:	045-15564	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	294666	Type:	WELL	API Number:	045-15565	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	294667	Type:	WELL	API Number:	045-15566	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	294668	Type:	WELL	API Number:	045-15567	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	294669	Type:	WELL	API Number:	045-15568	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

Producing Well

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
				Material Handling And Spill Prevention		
		Check Dams				
Gravel						
		Gravel				
		Culverts				
Compaction						
		Compaction				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708303633	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6984922