

Interim Reclamation and Stormwater Inspection

Date: 04/01/2025

Operator: MDS ENERGY DEVELOPMENT LLC - 10814

Location ID: 477495

Inspection Document #: 718700261

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Daffy Pad
Location ID: 477495



Photos 1 & 2. Erosion degradation previously observed along the access road appears to have been repaired.

Inspection Photos
Location Name: Daffy Pad
Location ID: 477495



Photos 3 & 4. Erosion degradation previously observed near the drilling pad entrance appears to have been repaired.

Inspection Photos
Location Name: Daffy Pad
Location ID: 477495



Photos 5 & 6. Photo 5 (left) taken from the northwest corner of the location, illustrating that undesirable vegetation previously observed, appears to have been managed for (e.g. mowed). Photo 6 (right) illustrates that concrete debris has been removed.

Inspection Photos
Location Name: Daffy Pad
Location ID: 477495



Photos 7 & 8. Taken from the western portion of the drilling pad. Photos illustrate that bare soils appeared to have been seeded for stabilization.

Inspection Photos
Location Name: Daffy Pad
Location ID: 477495



Photos 9 & 10. Taken from the southwest corner of the drilling pad. It appears that erosion degradation previously observed, appears to have been repaired.

Inspection Photos
Location Name: Daffy Pad
Location ID: 477495



Photos 11 & 12. Taken from the southeast corner of the drilling pad. Photo 11 (left) illustrates that undesirable vegetation appears to have been managed for in the stormwater ditch and topsoil stockpile. Photo 12 (right) illustrates that unstabilized soils south of the topsoil stockpile appear to have been seeded; trash and debris also removed.

Inspection Photos
Location Name: Daffy Pad
Location ID: 477495



Photos 13 & 14. South side of topsoil stockpile. Undesirable vegetation appears to have been removed and bare soil stabilized with seeding.

Inspection Photos
Location Name: Daffy Pad
Location ID: 477495



Photos 15 & 16. Stormwater control measures do not appear to be adequate as degradation is evident and straw wattles are beginning to fill with sediment.

Inspection Photos
Location Name: Daffy Pad
Location ID: 477495



Photos 17 & 18. Erosion degradation within the stormwater ditch (northwest corner of location) appear to have been repaired.



Photo 19. No apparent stormwater control measures observed on the north end of the location that would prevent sediment laden stormwater from exiting off location, into the culvert underneath CO HWY 14 (indicated by red arrow).

Inspection Photos
Location Name: Daffy Pad
Location ID: 477495



Photos 20 & 21. Cellar covers appear to have been installed around each well location.