

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/08/2025

Submitted Date:

04/08/2025

Document Number:

716300826

FIELD INSPECTION FORMLoc ID 333672 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

ECMC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	Insp. w/ca's
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271048	WELL	SI	12/01/2024	GW	071-07972	MAGIC 14-4	SI
273656	WELL	PR	12/29/2004	CBM	071-08199	MAGIC 14-4 TR	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

PHOTO 5: OILY WASTE IN TR WELL PRIME MOVER ENGINE SKID.

Corrective Action:

DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE OR TREAT IMPACTED SOIL PER RULE 1002.(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.

Date: 04/09/2025Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Separator

2

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

9

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

2

Comment:

Corrective Action:

Date:

Type: Prime Mover

2

Comment:

Corrective Action:

Date:

Type: Progressive Cavity

2

Comment:

Corrective Action:

Date:

Type: Bradenhead

2

Comment:

BOTH ARE ACCESSABLE

Corrective Action:

Date:

Type: Ancillary equipment

2

Comment:

Corrective Action:

Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 271048 Type: WELL API Number: 071-07972 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 11/11/2011 Annual Brhd Completed? _____Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0Comment: FORM 4 ON FILE

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 273656 Type: WELL API Number: 071-08199 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 11/11/2011 Annual Brhd Completed? _____Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0Comment: FORM 4 ON FILE

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 278935Lat: 37.281900Long: -104.793048Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Action: Date: Type: Produced WaterLined: NOPit ID: 278531Lat: 37.281900Long: -104.793048Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition:

Comment:				Date:
Corrective Action				
Anchor Trench Present: <u>NO</u> Oil Accumulation: <u>NO</u> 2+ feet Freeboard: <u>YES</u>				
Comment:				Date:
Corrective Action				
Permit:	Facility ID	Permit Num	Expiration Date	
	278935	1445924		
	278531	1175488		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716300827	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6995502