

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 44-18 pad

Location ID: 335146



Photo # 9334 From entrance to location




Photo # 9335 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 44-18 pad

Location ID: 335146



Photo # 9336 Location



Photo # 9337 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 44-18 pad

Location ID: 335146




Photo # 9338 Location



Photo # 9339 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 44-18 pad

Location ID: 335146



Photo # 9340 Unused equipment



Photo # 9341 Wellhead sign weathered & peeling



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 44-18 pad

Location ID: 335146




Photo # 9342 Wellhead sign weathered & peeling




Photo # 9343 Wellhead sign weathered & starting to peel