

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2025

Submitted Date:

04/08/2025

Document Number:

708303664

**FIELD INSPECTION FORM**

Loc ID: 335118 Inspector Name: Morris, Matthew On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
 11 Number of Comments  
 1 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 ECMC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: 1058 COUNTY ROAD 215  
 City: PARACHUTE State: CO Zip: 81635

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

Data retrieval failed for the subreport, 'Subreport2'.

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260917	WELL	PR	03/01/2011	GW	045-07921	PORTER FEDERAL 16-29	PR
260919	WELL	PR	12/10/2008	GW	045-07923	PORTER FEDERAL 9-29	PR
285049	WELL	PR	11/06/2007	GW	045-12359	SHIDELER FEDERAL 44B-29-692	PR
285050	WELL	PR	11/03/2007	GW	045-12360	SHIDELER FEDERAL 43D-29-692	PR
285051	WELL	PR	11/04/2007	GW	045-12361	SHIDELER FEDERAL 43A-29-692	PR
291190	WELL	PR	12/09/2014	GW	045-14317	SHIDELER FEDERAL 44A-29-692	PR

**General Comment:**

[CECMC Audit Report Summary](#)

On 4/3/2025 at approximately 11:30, Compliance Inspector Matthew Morris conducted a follow-up audit at TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/29SESE at Location ID #335118 in Garfield County, Colorado.

During the audit, the following compliance issues were observed:

1) Unused equipment; unused chemical tank near wellheads

A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused chemical tank near wellheads.		
Corrective Action:	Remove unused equipment.	Date:	04/16/2025

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	IGNITOR/COMBUSTOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks. One tank is unused.		
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal						
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	HEATED STEEL AST		,	
Comment:		Staining present on insulation of condensate tanks. Unable to verify integrity of tank walls.				
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal						
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

<b>Inspected Facilities</b>			
Facility ID: <u>260917</u>	Type: <u>WELL</u>	API Number: <u>045-07921</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			Date:
Corrective Action:			Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>260919</u>	Type: <u>WELL</u>	API Number: <u>045-07923</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			Date:
Corrective Action:			Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>285049</u>	Type: <u>WELL</u>	API Number: <u>045-12359</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			Date:
Corrective Action:			Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>285050</u>	Type: <u>WELL</u>	API Number: <u>045-12360</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			Date:
Corrective Action:			Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>285051</u>	Type: <u>WELL</u>	API Number: <u>045-12361</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			Date:
Corrective Action:			Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>291190</u>	Type: <u>WELL</u>	API Number: <u>045-14317</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			Date:
Corrective Action:			Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
				Material Handling And Spill Prevention		
		Ditches				
Berms						
		Culverts				
		Gravel				
Gravel						
		Check Dams				
		Compaction				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708303665	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6995624">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6995624</a>