



067-06141

Dakota Fee 1

4/7/2025 photos



Dried cement and oily residue with
casing bubbling from inside, casing
not capped



04.07.2025

Cementing residue/washout



04.07.2025

Oily boom material



04.07.2025

Tank berms still present



04.07.2025

Imported topsoil?



04.07.2025

Imported topsoil?



04.07.2025