

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 12-28 Pad

Location # 335266



Photo # 615 From entrance to location




Photo # 616 Location

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 12-28 Pad

Location # 335266



Photo # 617 Location



Photo # 618 Location



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 12-28 Pad

Location # 335266



Photo # 619 Location



Photo # 620 Location



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 12-28 Pad

Location # 335266



Photo # 621 Location



Photo # 622 PRV vent line does not comply with CECMC pressure safety device rules or general safety rules



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 12-28 Pad

Location # 335266



**Photo # 623 Tank is disconnected & not in use/unused equipment**



**Photo # 624 Tank is disconnected & not in use/unused equipment**



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 12-28 Pad

Location # 335266



**Photo # 625 Tank is disconnected & not in use/unused equipment**



**Photo # 626 Tank is disconnected & not in use/unused equipment**