

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/31/2025

Submitted Date:

04/08/2025

Document Number:

716300771**FIELD INSPECTION FORM**Loc ID 334202 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	<a href="#">Insp. w/ca's</a>
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270572	WELL	PR	08/01/2021	GW	071-07945	STONES 24-8	PR
291217	WELL	PR	03/01/2008	CBM	071-09346	STONES 24-8 TR	PR
301251	PIT	AC	12/23/2009		-	STONES 24-8 TR	AC

**General Comment:**

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:					
Corrective Action:				Date: _____	
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:				corrective date	
Type: Prime Mover		# 2			
Comment:					
Corrective Action:					Date:
Type: Deadman # & Marked		# 8			
Comment:					
Corrective Action:					Date:
Type: Ancillary equipment		# 2			
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run		# 2			
Comment:		BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.			
Corrective Action:					Date:
Type: Progressive Cavity		# 2			
Comment:					
Corrective Action:					Date:
Type: Bradenhead		# 2			
Comment:		BOTH ARE ACCESSABLE			
Corrective Action:					Date:
Type: Vertical Separator		# 2			
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					

Type		
Comment:		
Corrective Action:		Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 301251Lat: 37.267695Long: -104.804371Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: InadequateComment: PHOTO 4: pit liner compromised (Rule 910).Corrective Action Reduce fluid level in pit, contact ECMC EPS staff for directives.Date: 04/09/2025**Fencing:**Fencing Type: Fencing Condition: AdequateComment: Corrective Action Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action Date: Anchor Trench Present: YESOil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Action Date: **Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404157965	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6995509">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6995509</a>
716300814	INSP. PHOTOS	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6995485">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6995485</a>