

Inspection Photos

Location Name: QB Energy SAVAGE 2-31 (RL2) Pad

Location #: 324005



Photo # 1273 From Entrance to location




Photo # 1274 Location

Inspection Photos
Location Name: QB Energy SAVAGE 2-31 (RL2) Pad
Location #: 324005



Photo # 1275 Location



Photo # 1276 Location

Inspection Photos
Location Name: QB Energy SAVAGE 2-31 (RL2) Pad
Location #: 324005



Photo # 1277 Location



Photo # 1278 Location

Inspection Photos
Location Name: QB Energy SAVAGE 2-31 (RL2) Pad
Location #: 324005



Photo # 1279 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity



Photo # 1280 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity

Inspection Photos
Location Name: QB Energy SAVAGE 2-31 (RL2) Pad
Location #: 324005



Photo # 1281 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity

Photo # 1282 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity

Inspection Photos

Location Name: QB Energy SAVAGE 2-31 (RL2) Pad

Location #: 324005



Photo # 1283 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity