

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2025

Submitted Date:

04/15/2025

Document Number:

708303702

FIELD INSPECTION FORM

Loc ID 335467 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Smelser, Wayne		wayne.smelser@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293618	WELL	PR	06/19/2008	GW	045-15071	GGU VAN ORDSTRAND 23B-30-691	PR
293625	WELL	SI	01/01/2025	GW	045-15072	GGU VANORDSTRAND 33D-30-691	SI
293626	WELL	PR	06/23/2008	GW	045-15073	GGU VANORDSTRAND 23C-30-691	PR
293627	WELL	PR	06/10/2008	GW	045-15074	GGU VANORDSTRAND 33B-30-691	PR
293629	WELL	PR	06/22/2008	GW	045-15075	GGU VANORDSTRAND 23D-30-691	PR
293632	WELL	PR	06/01/2017	GW	045-15076	GGU VANORDSTRAND 34D-30-691	PR

General Comment:

[CECMC Audit Report Summary](#)

On 4/9/2025 at approximately 13:15, Compliance Inspector Matthew Morris conducted a follow-up audit at TEP ROCKY MOUNTAIN LLC, GGU VAN ORDSTRAND-66S91W/30NESW at Location ID #335467 in Garfield County, Colorado.

During the audit, the following compliance issues were observed:

- 1) Illegible wellhead signs

A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Wellhead signs are illegible.		
Corrective Action:	Install signs to comply with Rule 605.d.	Date:	05/16/2025

Emergency Contact Number:

Comment:	911/(970)285-9377	Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 293618 Type: WELL API Number: 045-15071 Status: PR Insp. Status: PR

Producing Well

Comment:	
Corrective Action:	Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293625 Type: WELL API Number: 045-15072 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last produced November 2024 per production report.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293626 Type: WELL API Number: 045-15073 Status: PR Insp. Status: PR

Producing Well

Comment:	
Corrective Action:	Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293627 Type: WELL API Number: 045-15074 Status: PR Insp. Status: PR

Producing Well

Comment:	
Corrective Action:	Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293629 Type: WELL API Number: 045-15075 Status: PR Insp. Status: PR

Producing Well

Comment:	
Corrective Action:	Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293632 Type: WELL API Number: 045-15076 Status: PR Insp. Status: PR

Producing Well

Comment:	
Corrective Action:	Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
Culverts						
		Gravel				
		Check Dams				
Compaction						
Gravel						
		Culverts				
		Ditches				
		Compaction				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708303703	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7006539