

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2025

Submitted Date:

04/09/2025

Document Number:

717701289

**FIELD INSPECTION FORM**

Loc ID 437628 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437627	TANK BATTERY	AC	06/17/2014		-	Consolidation Unit # 8 437627	AC

**General Comment:**

[This is an audit due to complaints](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Unmarked Riser needs to be marked. See attached photos.		
Corrective Action:	Comply with the 1100 rules	Date:	04/25/2025

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 437627 Type: TANK API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment: [Active Facility](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Optical Gas Imaging Survey**

Survey Type: Complaint

Current Operations:  Production  Workover  Flowback  Referred to APCD

GPS(entrance of location): Lat: 40.081600 Long: -104.848600

Wind: Light Speed: 9 (mph) Direction From: sw Weather: Cloudy Temperature: 53 (F)

Assisting Staff: Brittani Santistevan Camera #: 2

Visible Smoke  Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
-------------------	-------	-----------------	-------

Equipment
Oil Tank(s)
Water Tank(s)
Separation Equipment
Other

Comment: Pressure Relief Valve on the water tank appears to be leaking. Fix or replace.

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 04/25/2025

**ECMC Comments**

Comment	User	Date
<p><b>ECMC Audit Report Summary</b></p> <p>On Tuesday, April 8th, 2025, at approximately 9:12 AM, Inspector Adam Burns conducted an on-site audit at the following location:</p> <p>Facility: Consolidation Unit #8 437627                      Operator: KP Kauffman Company Inc.                      Facility ID #437627                      County: Weld</p> <p>During the audit, the following possible compliance issues were identified:                      Unmarked Riser: Unmarked Riser needs to be marked. Comply with the 1100 rules.                      Mechanical Conditions: Pressure Relief Valve on the water tank appears to be leaking. Fix or replace. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.                      A follow-up audit is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules.                      Please note that any corrective actions from previous audits that have not been addressed remain applicable.</p>	burnsa	04/09/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404158423	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996193">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996193</a>
717701290	Flir Video on Tanks	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996165">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996165</a>
717701291	Drone OGI camera	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996166">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996166</a>
717701292	Flir Video	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996169">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996169</a>
717701293	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996173">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996173</a>