

**Operator:** CRESTONE PEAK RESOURCES OPERATING LLC

**Location Name:** PURITAN 4-4-34

**Loc ID:** 336332

**Inspection:** 718600249



**Exhibit A**



**Exhibit B**

**CA:** An in process Form 44 (Doc Id #402543661) submitted 12/01/2020 indicates the flowline between Puritan #33-34 (Loc ID #336332) and PURITAN/2N68W/34SESE (Loc ID #336413) was flushed and abandoned in place. There are three fenced open excavations around the wellbore. It appears the open excavations may be related to flowline abandonment. See attached photos. Continue to work with ECMC engineering staff for Form 44 approval. Fill and reclaim excavations according to Rule 1004.

**CA Resolution:** Operator has backfilled all holes on pad and addressed fencing in order to comply with Rule 1004.