

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY # 4 Pad

Location ID: 335514



Photo # 2482 From entrance to location




Photo # 2483 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY # 4 Pad

Location ID: 335514



Photo # 2484 Location



Photo # 2485 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY # 4 Pad

Location ID: 335514



Photo # 2486 Location



Photo # 2487 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY # 4 Pad

Location ID: 335514



**Photo # 2488 Possible tank failure - Suspected leaks on production tank/tank appears to lack integrity**



**Photo # 2489 Possible tank failure - Suspected leaks on production tank/tank appears to lack integrity**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY # 4 Pad

Location ID: 335514



**Photo # 2490 Possible tank failure - Suspected leaks on production tank/tank appears to lack integrity**



**Photo # 2491 Possible tank failure - Suspected leaks on production tank/tank appears to lack integrity**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY # 4 Pad

Location ID: 335514



**Photo # 2492 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity**



**Photo # 2493 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY # 4 Pad

Location ID: 335514



**Photo # 2494 Possible tank failure - Suspected leaks on production tank/tank appears to lack integrity**



**Photo # 2495 PRV vent line does not comply with CECMC pressure safety device rules or general safety rules**