

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 23-16 Pad

Location ID: 335447



Apr 16, 2025 at 11:15:13 AM
CO



Apr 16, 2025 at 11:20:08 AM
CO

Photo # 1632 From entrance to location

Photo # 1633 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 23-16 Pad

Location ID: 335447



Photo # 1634 Location



Photo # 1635 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 23-16 Pad

Location ID: 335447



Photo # 1636 Location



Photo # 1637 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 23-16 Pad

Location ID: 335447



Photo # 1638 Open ended load line



Photo # 1639 PRV vent line does not comply with CECMC pressure safety rules or general safety rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 23-16 Pad

Location ID: 335447



Photo # 1640 PRV vent line does not comply with CECMC pressure safety rules or general safety rules



Photo # 1641 Battery sign weathered & illegible/not in compliance with CECMC rules