

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 33-21 Pad

Location ID: 335507



Photo # 1957 From entrance to location




Photo # 1958 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 33-21 Pad

Location ID: 335507



Photo # 1959 Location



Photo # 1960 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 33-21 Pad

Location ID: 335507



Photo # 1961 Location



Photo # 1962 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 33-21 Pad

Location ID: 335507



Photo # 1963 Location



Photo # 1964 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 33-21 Pad

Location ID: 335507



Photo # 1965 Open ended load line



Photo # 1966 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 33-21 Pad

Location ID: 335507



Photo # 1967 Open ended load line



Photo # 1968 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 33-21 Pad

Location ID: 335507



Photo # 1969 Open ended load line



Photo # 1970 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 33-21 Pad

Location ID: 335507



Photo # 1971 Open ended load line



Photo # 1972 PRV vent line does not comply with CECMC pressure safety rules or general safety rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 33-21 Pad

Location ID: 335507



Photo # 1973 PRV vent line does not comply with CECMC pressure safety rules or general safety rules



Photo # 1974 PRV vent line does not comply with CECMC pressure safety rules or general safety rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 33-21 Pad

Location ID: 335507



Photo # 1975 PRV vent line does not comply with CECMC pressure safety rules or general safety rules



Photo # 1976 Rusted pup joint/debris