

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2025

Submitted Date:

04/13/2025

Document Number:

708906243**FIELD INSPECTION FORM**

Loc ID 323980	Inspector Name: Smelser, Wayne	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 17 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> ECMC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>1058 COUNTY ROAD 215</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
TEP		COGCCInspectionReports@terraep.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211400	WELL	PR	06/12/1997	GW	045-07160	GIBSON GULCH UNIT 15-30	PR

**General Comment:**

CECMC Inspection/Audit Report Summary  
 On 04/10/2025 at approximately 13:29 hours, I, Compliance Specialist, Wayne Smelser  
 Conducted a follow up inspection/audit at TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 15-30 Pad.  
 Location # 323980 in Garfield County Colorado.  
 Please refer to inspection/audit 708903649 conducted on 04/25/2024, previous corrective actions have been completed.  
 Location is within High Priority/Density/NSO/Black Bear Habitat areas.  
 While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Equipment - Bird protection damaged & needs maintenance/wildlife hazard with a CA date of 04/20/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.  
 This is a summary of inspection/audit report

Split pad/Remote location - Shared facilities with the GIBSON GULCH UNIT 15-30 D, location # 324014

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at intersection of CR 311 & lease road		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panels & cattle panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels & barbed wire		
Corrective Action:		Date:	

Type	WELLHEAD		
Comment:	Hog panels & cattle panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Bird protection on 1 separator is damaged & needs maintenance/wildlife hazard		
Corrective Action:	Comply with CECMC wildlife rules	Date:	04/20/2025
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	200 BBLS	STEEL AST		,	
Comment:	Tank is not equipped with telemetry					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	211400	Type:	WELL	API Number:	045-07160	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Ditches				
Gravel						Sparse to none in areas
		Culverts				
		Gravel				Sparse to none
		Compaction				Light compaction in some areas

Comment: Erosion & transport of sediment on lease road/road degradation on portion of lease road going to the GIBSON GULCH UNIT 15-30 D. Sediment is being transported from the lease road onto this location, please refer to inspection 708906240 for Stormwater corrective action.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
Please refer to Equipment for corrective action & also refer to inspection 708906240 for Stormwater corrective action.	smelserw	04/13/2025
Split pad/Remote location - Shared facilities with the GIBSON GULCH UNIT 15-30 D, location # 324014		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404162745	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7002678">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7002678</a>
708906244	Inspection/Audit 708906243 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7002676">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7002676</a>
708906246	Inspection/Audit 708906243 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7002677">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7002677</a>