



067-07759

Crader 3-2 Photo document

4/15/2025



04.15.2025

Northwest corner of location



04.15.2025

Erosion channel and sediment run on



04.15.2025

Run on control berm not functioning
and allowing water to onto location



Area where run on control failure is allowing stormwater from other channel onto location

04.15.2025



04.15.2025



04.15.2025



04.15.2025

Sediment migration onto pad



04.15.2025

Erosion of east side of location



04.15.2025

Stormwater erosion going off pad



04.15.2025



04.15.2025



04.15.2025



04.15.2025

Check dams south side eof location



04.15.2025

Rock run down south side of location



04.15.2025

Ditch and berm west side of location