

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/15/2025

Submitted Date:

04/21/2025

Document Number:

700300803**FIELD INSPECTION FORM**Loc ID 326276 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10663Name of Operator: ENDURING RESOURCES LLCAddress: 6300 S SYRACUSE WAY, SUITE 525City: CENTENNIAL State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Walter, Kyle		kwalter@enduringresources.com	<a href="#">AIISW Inspections</a>
Huntington, Heather		hhuntington@enduringresources.com	<a href="#">All SW Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216153	WELL	PR	02/04/2000	CBM	067-07759	CRADER 3-2	PR

**General Comment:**

On April 15, 2025 SW Compliance Supervisor Steve Labowskie performed a stormwater inspection of the Crader 3-2 location referred by Compliance Inspector Charles Garcia. This inspection does not address equipment or open corrective actions.

See Stormwater section for corrective action in regards to stormwater BMP maintenance and management of run-on and run-off.

Location				
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	216153	Type:	WELL	API Number:	067-07759	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Compaction	Pass			
Check Dams	Pass					
Rip Rap	Pass					
		Gravel	Pass			
Berms	Fail					

Comment: Breached area of run on control berm on NW corner of location (see slides 3 nd 4) with erosion and sediment migration (slide 8) onto pad. It appears that during storm evfents, water flows across pad and exits in the middle of east side and is causing erosion on the outlet (slides 9, 10 and 11). Other erosion control berms, check dams and rock run downs are maintained.

Corrective Action: Repair and maintain BMPs and minimize erosion and sediment migration at run on and run off areas per Rule 1002.f

Date: 05/21/2025

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700300804	INSPECTION PHOTOS	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7013754">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7013754</a>