

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2025

Submitted Date:

04/15/2025

Document Number:

708303700

**FIELD INSPECTION FORM**Loc ID 335294 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smelser, Wayne		wayne.smelser@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211401	WELL	PR	08/15/1997	GW	045-07161	GIBSON GULCH UNIT 11-30	PR
268139	WELL	PR	08/11/2003	GW	045-09243	GIBSON GULCH UNIT 7-30 C	PR

**General Comment:****CECMC Audit Report Summary**

On 4/9/2025 at approximately 13:05, Compliance Inspector Matthew Morris conducted a follow-up audit at TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30NESW at Location ID #335294 in Garfield County, Colorado.

During the audit, the following compliance issues were observed:

- 1) Stored supplies (load hose) in tank containment poses a wildlife entry hazard

A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/(970)285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Refer to FIR #696206108.  It was observed in this inspection that hay bales are being stored within close proximity of production equipment, on the south end of the Location; this is a potential fire hazard.		
Corrective Action:	The storage or placement of materials, and all other supplies not necessary for use on an Oil and Gas Location is prohibited. Coordinate with the Surface Owner and relocate hay bales off of Location and away from production equipment.	Date:	08/28/2024
Type	STORAGE OF SUPL		
Comment:	Stored load hose in tank containment poses a wildlife entry hazard.		
Corrective Action:	Remove stored supplies from location.	Date:	04/23/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	WELLHEAD		

Comment:	Cattle panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Cattle panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal					
Comment:	Patch on berm liner is beginning to peel away from liner.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:	Patch on berm liner is beginning to peel away from liner.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLS	STEEL AST		,

Comment:				
Corrective Action:				Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:	Patch on berm liner is beginning to peel away from liner.			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211401	Type:	WELL	API Number:	045-07161	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	268139	Type:	WELL	API Number:	045-09243	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Compaction						
		Gravel				
		Ditches				
		Compaction				
		Check Dams				
Berms						
		Culverts				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404166502	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7006548">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7006548</a>
708303701	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7006538">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7006538</a>