

# Final Reclamation and Stormwater Inspection

Date: 04/17/2025

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 312263

Inspection Document #: 718700332

Logan County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Emerald Unit  
Location ID: 312263



**Photos 1 & 2.** South side of the production facilities. It does not appear that the former tank battery has been reclaimed with evidence of undesirable vegetation and road base throughout.



Inspection Photos  
Location Name: Emerald Unit  
Location ID: 312263



**Photos 3 & 4.** North side of the production facilities. It does not appear that the former tank battery has been reclaimed with evidence of undesirable vegetation and road base throughout.



Inspection Photos  
Location Name: Emerald Unit  
Location ID: 312263



**Photos 5 & 6.** Middle/center portion of the production facilities. It does not appear that the former tank battery has been reclaimed with evidence of undesirable vegetation and road base throughout.



Inspection Photos  
Location Name: Emerald Unit  
Location ID: 312263



**Photos 7 & 8.** Utilities do not appear to have been removed at the former tank battery. Also pictured, open excavation near utilities (indicated by red arrow).



Inspection Photos  
Location Name: Emerald Unit  
Location ID: 312263



**Photos 9 & 10.** Cattle guard remains and access road to pit does not appear to have been reclaimed.



Inspection Photos  
Location Name: Emerald Unit  
Location ID: 312263



**Photos 11 & 12.** Produced water pit does not appear to be in active use and has not been reclaimed.



Inspection Photos  
Location Name: Emerald Unit  
Location ID: 312263



**Photos 13 & 14.** Erosion degradation and no observed stormwater control measures/BMPs around pit perimeter.



Inspection Photos  
Location Name: Emerald Unit  
Location ID: 312263



**Photos 15 & 16.** No perimeter stormwater control measures observed around the active remediation project near the former well location. Unknown stockpile does not have any stormwater control measures/BMPs.



Inspection Photos  
Location Name: Emerald Unit  
Location ID: 312263



**Photos 17 & 18.** Former access road to the well location does not appear to have been reclaimed.



Inspection Photos  
Location Name: Emerald Unit  
Location ID: 312263



**Photos 19 & 20.** Utilities near the former well location do not appear to have been removed.

Inspection Photos  
Location Name: Emerald Unit  
Location ID: 312263



**Photos 21 & 22.** No perimeter stormwater control measures observed around the active remediation project near the former well location.