

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/21/2025

Submitted Date:

04/21/2025

Document Number:

716300881

FIELD INSPECTION FORMLoc ID 333380 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------------|--------------|----------------------------|---------------------------------|
| Distribution, Evergreen | 719-846-7898 | cogcc.evergreen@enrllc.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 286325 | WELL | PR | 07/11/2008 | CBM | 071-08945 | MACGREGOR 32-25 TR | PR |
| 286327 | WELL | PR | 07/14/2008 | CBM | 071-08944 | MACGREGOR 32-25 | PR |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| Type | Area | Volume |
|------|------|--------|
| | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Separator

2

Comment:

Corrective Action:

Date:

Type: Progressive Cavity

2

Comment:

Corrective Action:

Date:

Type: Compressor

1

Comment: TR WELL

Corrective Action:

Date:

Type: Prime Mover

2

Comment:

Corrective Action:

Date:

Type: Bradenhead

2

Comment: BOTH ARE ACCESSABLE

Corrective Action:

Date:

Type: Gas Meter Run

2

Comment: BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Ancillary equipment

2

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

6

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Gravel | Pass | Gravel | Pass | | | |
| Compaction | Pass | Culverts | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| | | |
|--------------|--------------|---|
| Document Num | Description | URL |
| 716300882 | INSP. PHOTOS | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7019021 |