

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/07/2025

Submitted Date:

04/24/2025

Document Number:

698603404

FIELD INSPECTION FORMLoc ID 304997 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|--------------|------------------------------|---------|
| Dolezal, Pat | 970-332-3585 | pat.dolezal@ownresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 277469 | WELL | PR | 05/27/2005 | GW | 125-09242 | PAGEL 43-34-4N47W | PR |

General Comment:

Routine Inspection.

| Location | | | | |
|--|---|--------|-----------------|--|
| <u>Lease Road:</u> | | | | |
| Type | Access | | | |
| comment: | Two track off maintained County Road. Active agricultural cropland with seasonal access to well location. | | | |
| Corrective Action | | | Date: | |
| Overall Good: <input type="checkbox"/> | | | | |
| <u>Signs/Marker:</u> | | | | |
| Type | WELLHEAD | | | |
| Comment: | Lease sign at wellhead location. | | | |
| Corrective Action: | | | Date: | |
| Type | BATTERY | | | |
| Comment: | Lease sign posted at remote Gas Meter Run. | | | |
| Corrective Action: | | | Date: | |
| Emergency Contact Number: | | | | |
| Comment: | Emergency contact information posted on Lease sign. | | | |
| Corrective Action: | | | Date: | |
| <u>Good Housekeeping:</u> | | | | |
| Type | UNUSED EQUIPMENT | | | |
| Comment: | Removed Pump Jack drive belt guard noted inside wellhead fencing. | | | |
| Corrective Action: | | | Date: | |
| Overall Good: <input type="checkbox"/> | | | | |
| <u>Spills:</u> | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: <input style="width: 100%;" type="text"/> | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| <u>Fencing/:</u> | | | | |
| Type | WELLHEAD | | | |
| Comment: | Stock panel fencing around surface equipment at well location. | | | |
| Corrective Action: | | | Date: | |
| <u>Equipment:</u> | | | | |
| | | | corrective date | |
| Type: Prime Mover | # 1 | | | |
| Comment: | Electric Motor. | | | |
| Corrective Action: | | | Date: | |
| Type: Other | # 1 | | | |
| Comment: | Pump Jack welded steel pipe base. | | | |
| Corrective Action: | | | Date: | |
| Type: Other | # 1 | | | |
| Comment: | Shared Remote Gas Meter Shed. Door handle is broken and door is jammed shut. | | | |

| | | | |
|---------------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Remote Gas Meter Run located on CR M & Pagel 1-36 access at shared gathering location. Gas Meter Run. Meter shed door is broken and no access to meter. Well Inlet Valve open. Gas Outlet Valve open. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Pump Jack Power and Control Panel. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve closed. Casing valve open. | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Bradenhead plumbed to surface. | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 277469 | Type: | WELL | API Number: | 125-09242 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Rods and tubing in wellbore. Tubing valve closed. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open. Electronic Well File reflects last Production/Status reported 2/1/2025 and Well Status as PR. Based on current valve settings at time of inspection the well is PR. | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Compaction | Pass | Compaction | Pass | | | |

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| | | |
|--------------|--------------------|---|
| Document Num | Description | URL |
| 698603418 | Inspection photos. | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7020329 |