

Inspection/Audit Photos
Location Name: QB Energy DUNN 32-16 (P32) Pad
Location ID: 334836



Photo # 6244 From entrance to location



Photo # 6245 Location

Inspection/Audit Photos
Location Name: QB Energy DUNN 32-16 (P32) Pad
Location ID: 334836



Photo # 6246 Location



Photo # 6247 Location



Inspection/Audit Photos
Location Name: QB Energy DUNN 32-16 (P32) Pad
Location ID: 334836



Photo # 6248 Location




Photo # 6249 Location

Inspection/Audit Photos
Location Name: QB Energy DUNN 32-16 (P32) Pad
Location ID: 334836



Photo # 6250 Location



Photo # 6251 Location

Inspection/Audit Photos
Location Name: QB Energy DUNN 32-16 (P32) Pad
Location ID: 334836



Photo # 6252 Weeds in secondary containment



Photo # 6253 Weeds in secondary containment

Inspection/Audit Photos
Location Name: QB Energy DUNN 32-16 (P32) Pad
Location ID: 334836



Photo # 6254 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity



Photo # 6255 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity

Inspection/Audit Photos
Location Name: QB Energy DUNN 32-16 (P32) Pad
Location ID: 334836



Photo # 6256 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity



Photo # 6257 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity

Inspection/Audit Photos
Location Name: QB Energy DUNN 32-16 (P32) Pad
Location ID: 334836



Photo # 6258 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity



Photo # 6259 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity

Inspection/Audit Photos
Location Name: QB Energy DUNN 32-16 (P32) Pad
Location ID: 334836



Photo # 6260 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity



Photo # 6261 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity

Inspection/Audit Photos
Location Name: QB Energy DUNN 32-16 (P32) Pad
Location ID: 334836



Photo # 6262 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity



Photo # 6263 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity

Inspection/Audit Photos

Location Name: QB Energy DUNN 32-16 (P32) Pad

Location ID: 334836



Photo # 6264 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity



Photo # 6265 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity

Inspection/Audit Photos
Location Name: QB Energy DUNN 32-16 (P32) Pad
Location ID: 334836



Photo # 6266 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity



Photo # 6267 Possible tank failure - Suspected leak on production tank/tank appears to lack integrity