

Inspection/Audit Photos

Location Name: QB Energy SHIDELER 33-4D (E33NE) Pad

Location ID: 335019



Photo # 5664 From entrance to location




Photo # 5665 Location



Inspection/Audit Photos

Location Name: QB Energy SHIDELER 33-4D (E33NE) Pad

Location ID: 335019



Photo # 5666 Location



Photo # 5667 Location

Inspection/Audit Photos

Location Name: QB Energy SHIDELER 33-4D (E33NE) Pad

Location ID: 335019



Photo # 5668 Location



Photo # 5669 Location

Inspection/Audit Photos

Location Name: QB Energy SHIDELER 33-4D (E33NE) Pad

Location ID: 335019



Photo # 5670 Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 5671 Rupture disc vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: QB Energy SHIDELER 33-4D (E33NE) Pad

Location ID: 335019



Photo # 5672 Unused flowlines lack lockout tagout (OOSLAT)



Photo # 5673 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: QB Energy SHIDELER 33-4D (E33NE) Pad

Location ID: 335019



Photo # 5674 Unmarked deadman



Photo # 5675 Same unmarked deadman

Inspection/Audit Photos

Location Name: QB Energy SHIDELER 33-4D (E33NE) Pad

Location ID: 335019



Apr 24, 2025 at 1:53:04 PM
CO

Photo # 5676 Same unmarked deadman from a different angle



Apr 24, 2025 at 1:36:58 PM
CO

Photo # 5677 Flowline heating insulation open ended /wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location Name: QB Energy SHIDELER 33-4D (E33NE) Pad

Location ID: 335019



Photo # 5678 Hole in liner/liner needs maintenance



Photo # 5679 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB Energy SHIDELER 33-4D (E33NE) Pad

Location ID: 335019



Photo # 5680 Hole in liner/liner needs maintenance



Photo # 5681 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB Energy SHIDELER 33-4D (E33NE) Pad

Location ID: 335019




Photo # 5682 Hole in liner/liner needs maintenance



Photo # 5683 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB Energy SHIDELER 33-4D (E33NE) Pad

Location ID: 335019



Photo # 5684 Weeds in secondary containment



Photo # 5685 Weeds in secondary containment

Inspection/Audit Photos

Location Name: QB Energy SHIDELER 33-4D (E33NE) Pad

Location ID: 335019



Photo # 5686 Weeds in secondary containment



Photo # 5687 Entrance to location sign laying on the ground /not properly posted