

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404180717

Date Received:
04/28/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

QB Energy

ecmc.inspections@qb-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708906290

Inspection Date: 04/17/2025

FIR Submit Date: 04/19/2025

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335178

Location Name: STI-66S92W Number: 29NWNE County: _____

Qtrqtr: NWNE Sec: 29 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.502580 Longitude: -107.685030

FACILITY - API Number: 05-045-00 Facility ID: 335178

Facility Name: STI-66S92W Number: 29NWNE

Qtrqtr: NWNE Sec: 29 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.502580 Longitude: -107.685030

CORRECTIVE ACTIONS:

1 CA# 204253

Corrective Action: The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.

Date: 05/09/2025

Response: CA COMPLETED

Date of Completion: 04/24/2025

Operator Comment: Repaired damaged areas of liner material.

ECMC Decision: _____

Date: 04/26/2025

Date of Completion: 04/24/2025

Operator Comment:	Covered open flowline insulation.
----------------------	-----------------------------------

ECMC Decision:

ECMC Representative:	
----------------------	--

Comment:

Title: Compliance Date: 4/28/2025 9:44:59 AM

<u>Document Number</u>	<u>Description</u>
404180731	Open piping covered.
404180737	Liner repair

Page 2 of 2