

**Robert L Bayless Producer LLC
Weaver Ridge 23-14
Location #316493**



Open end tank valve. Oily waste and stained soil.

Open end tank valve. Oily waste and stained soil.

Robert L Bayless Producer LLC
Weaver Ridge 23-14
Location #316493



Covered staining. Open end tank valve.




Damaged and incomplete tank labels

Robert L Bayless Producer LLC
Weaver Ridge 23-14
Location #316493





Damaged and incomplete tank labels



Damaged and incomplete tank labels

Robert L Bayless Producer LLC
Weaver Ridge 23-14
Location #316493



Damaged and incomplete tank labels

Damaged and incomplete tank labels

**Robert L Bayless Producer LLC
Weaver Ridge 23-14
Location #316493**



Oily waste and staining

Oily waste and staining

**Robert L Bayless Producer LLC
Weaver Ridge 23-14
Location #316493**



Oily waste and staining



Missing required information

Robert L Bayless Producer LLC
Weaver Ridge 23-14
Location #316493




Debris. Staining.



Leaking equipment. Staining

Robert L Bayless Producer LLC
Weaver Ridge 23-14
Location #316493




Unprotected riser




Unprotected risers

**Robert L Bayless Producer LLC
Weaver Ridge 23-14
Location #316493**



Debris and oily waste



Oily waste

Robert L Bayless Producer LLC
Weaver Ridge 23-14
Location #316493



Oily waste and stained soil



Debris

Robert L Bayless Producer LLC
Weaver Ridge 23-14
Location #316493



Debris



Debris

Robert L Bayless Producer LLC
Weaver Ridge 23-14
Location #316493



Faded and illegible label



Debris

Robert L Bayless Producer LLC
Weaver Ridge 23-14
Location #316493



Debris



Oily waste. Safety hazard.

**Robert L Bayless Producer LLC
Weaver Ridge 23-14
Location #316493**



Location from East end



Location from West end