

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/29/2025

Submitted Date:

04/29/2025

Document Number:

696307520**FIELD INSPECTION FORM**Loc ID 435952 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435953	WELL	PR	09/01/2023	OW	123-38878	State Antelope D14-X44-2HNC	PR
435954	WELL	SI	01/01/2025	OW	123-38879	State Antelope 14-44-2HNC	SI
435955	WELL	PR	09/01/2023	OW	123-38880	State Antelope D-X-2HNC	PR
449330	WELL	PR	01/16/2019	OW	123-44262	State Antelope J24-2-14XRLNB	PR
449331	WELL	PR	02/06/2019	OW	123-44263	State Antelope 14-2-14XRLNB	PR
449332	WELL	PR	01/11/2019	OW	123-44264	State Antelope E-2-14XRLNB	PR
449333	WELL	PR	01/16/2019	OW	123-44265	State Antelope J14-2-14XRLNB	PR
454853	WELL	PR	03/01/2024	OW	123-46747	State Antelope 24-2-14XRLNB	PR

General Comment:[This is a Follow-Up to FIR 696306415 dated 06.14.2024 Field Compliance Audit](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked 1" Risers at South Wellheads - See photos		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities

Facility ID: 435953 Type: WELL API Number: 123-38878 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435954 Type: WELL API Number: 123-38879 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In☐ Temporarily Abandoned

Reminder:

Comment: SI

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435955 Type: WELL API Number: 123-38880 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449330 Type: WELL API Number: 123-44262 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449331 Type: WELL API Number: 123-44263 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449332 Type: WELL API Number: 123-44264 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449333 Type: WELL API Number: 123-44265 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	454853	Type:	WELL	API Number:	123-46747	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696307521	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7026946