

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2025

Submitted Date:

04/29/2025

Document Number:

709100511

FIELD INSPECTION FORM

Loc ID 312320 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

- 13 Number of Comments
- 10 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kyle Waggoner		kyle.waggoner@state.co.us	
Krystal Heibel		krystal.heibel@state.co.us	
Rogers, Bob	(719)767-3415/ (719) 431-0236	brogers@cogc.com	All Inspections
Kennedy, Herschel	(719) 767-3401/ (719) 671-3787	hkennedy@cogc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275837	WELL	PR	07/01/2022	OW	075-09340	SINDT 13	EI
312320	LOCATION	AC	08/29/2024		-	SINDT-610N52W 31SESW	EI

General Comment:

On April 11, 2025, ECMC Environmental Unit Staff Krystal Heibel inspected the [SINDT-610N52W 31SESW](#) location (Location ID: 312320), the [Sindt 13 wellhead \(API 05-075-09340\)](#) and pit on location.

This is a follow-up inspection, from the previous Environmental inspections conducted on [May 23, 2024 \(Inspection Doc#709100292\)](#) and [May 11, 2025 \(Inspection Doc# 709100492\)](#).

The work site is in close proximity to [Beall Creek](#).

Any corrective actions from previous forms that have not been addressed are still applicable. Photos are attached to document site conditions at the time of the inspection.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type			
Comment:	No NFPA placard on poly tank.		
Corrective Action:	Install sign to comply with CDPHE rules.	Date:	04/11/2025
Type	TANK LABELS/PLACARDS		
Comment:	Emergency contact number illegible from a distance from tanks		
Corrective Action:	Emergency contact number illegible from a distance from tanks Install sign to comply with Rule 605.h.	Date:	07/04/2024
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (metal fence, piping, black secondary containment trays, chemical barrels, metal stepover, bucket, wire) observed on location. See photo documentation.		
Corrective Action:	Comply with Rule 606	Date:	09/04/2024
Type	OTHER		
Comment:	E&P Waste (buckets of crude oil located within metal shed) not properly stored, handled, transported, treated, or disposed per Rule 905		
Corrective Action:	Handle waste in accordance with Rule 905 and conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).D.	Date:	09/04/2024
Type	TRASH		
Comment:	Trash observed throughout location.		
Corrective Action:	Comply with Rule 606.	Date:	09/04/2024
Type	OTHER		
Comment:	Wildlife protections devices (netting) not adequate on secondary containment of black plastic bins.		
Corrective Action:	Install or repair wildlife protection equipment.	Date:	09/04/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Comment:	Stained soil located throughout site, including outside the tank's secondary containment, within metal shed next to pump, outside of metal shed, next to wellheads. See photo documentation.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. In accordance with 913.d. (1) Operator will investigate impacts to soil, groundwater, and surface water as soon as the impacts are discovered. Additionally, Operator shall provide an explanation of how the volume of liquids spilled was calculated on a Form 19 Supplemental Report and comply with Rule 912 series rules for Spills and Releases.		Date: 06/06/2024
Comment:	Hydrocarbons spill/release observed from top and sides of tanks (next to metal shed connection). See photo documentation.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 07/04/2024

Comment:	Lube oil observed at the polish rod of wellhead (API 075-09340)		
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b. Immediately remove oily waste.	Date:	07/04/2024

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type:	#		
Comment:	Pit on location is unregistered with the current operator.		
Corrective Action:	Submit an eForm 15 Pit Report to update ECMC records with current information to comply with rule 908.	Date:	09/14/2024

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 275837 Type: WELL API Number: 075-09340 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 312320 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100512	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7027075