

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2025

Submitted Date:

05/02/2025

Document Number:

717300325

FIELD INSPECTION FORM

Loc ID 329476 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249606	WELL	SI	11/01/2023	GW	123-17409	MAYER 22-12L	PA
329476	LOCATION	AC			-	MAYER-63N67W 22NWSW	EG

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photo uploaded](#)

Inspected Facilities

Facility ID: 249606 Type: WELL API Number: 123-17409 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 329476 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well is plugged and abandoned (Mayer 22-12); ECMC form 42 notice of start of plugging operations doc #404164128 received on 04/14/2025. (1) Flowline riser observed at PA well area; AIP work is in progress. Remediation work (historical) is ongoing.	maclarej	05/02/2025
As outlined on ECMC form 19 spill report Doc #404179817 received on 04/28/2025: A release was identified due to fluid daylighting from the subsurface adjacent to the Mayer 22-12L wellhead during well servicing activities. This release has been controlled and is no longer active. The volume of the release is unknown.	maclarej	05/02/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300326	PA well; FL Riser	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7032897