

Inspection Photos

Loc: 488235

Operator: BNL (ENTERPRISE) INC

Inspection Date: 5/1/2025

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing east along the access road. The road will need to be maintained per 1002.f. rules.



Inspection Photos



Photo 2. Facing northwest along the pre-existing access road. The road will need to be maintained per 1002.f. rules.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:488235 | Date: 5/1/2025

Inspection Photos



Photo 3. Facing east toward the access road and location. Topsoil was not salvaged along the road to the location approximately 100 yards. Soils are heavily compacted in this area..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:488235 | Date: 5/1/2025

Inspection Photos



Photo 4. The well cellar does not have adequate fence installed to prevent livestock or wildlife entry.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:488235 | Date: 5/1/2025

Inspection Photos



Photo 5. Facing toward the cuttings trench. The cutting material has been placed into the open top tanks at the right side of photo.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:488235 | Date: 5/1/2025

Inspection Photos



Photo 6. Facing northwest along the east side of the location. The liner with the drill cuttings material has no containment to prevent stormwater from washing the material off the liner.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:488235 | Date: 5/1/2025

Inspection Photos



Photo 7. Facing southwest corner of the location. This is the down slope corner of the location. A sediment trap was dug out in this area but is no properly constructed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:488235 | Date: 5/1/2025

Inspection Photos



Photo 8. The sediment trap was dug out in this area has no diversion to direct flow to the sediment trap and does not have proper inlet/outlet.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:488235 | Date: 5/1/2025