



PHOTO 1: BOTH SKIDS HAVE BEEN CLEANED AND ALL OILY FLUIDS REMOVED. ALL OPERATING EQUIPMENT ON LOCATION HAS RECEIVED MECHANICAL MAINTENANCE. THE IMPACTED SOILS HAVE BEEN REMOVED AND THE SELF INSPECTION PROCESS REVIEWED.