

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2025

Submitted Date:

05/06/2025

Document Number:

715501671

FIELD INSPECTION FORMLoc ID 312976 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10407

Name of Operator: ANTLER ENERGY LLC

Address: PO BOX 104

City: BAGGS State: WY Zip: 82321

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Evans, Clay	(307) 380-7616	clay@antler-energy.com	
Haverkamp, Curtis	(720) 786-5560	curtis.haverkamp@state.co.us	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Hoak, Thomas	(720) 594-8372	thomas.hoak@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
112983	PIT	AC	09/23/1999		-	FEDERAL MOUNTAIN FUEL 2-12	AC
223136	WELL	PR	08/01/2024	GW	081-06498	FEDERAL MOUNTAIN FUEL 2 12	PR

General Comment:**ECMC Inspection Report Summary**

On Tuesday, 05/06/2025, Inspector Kirby Burchett, was on location for a follow up field inspection at Antler Energy LLC on the Federal Mountain Fuel 2-12 well, Location #312976, in Moffat County, Colorado.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District with High Priority, NSO, and Density, and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #715500818 on 10/15/24 and Insp. #715501301 on 2/18/25. Operator submitted FIRR #404176706 on 4/23/25 addressing all compliance issues from 2/18/25 inspection. The following Corrective Action is still unresolved and original due date remains:

1. Unused equipment on location.
- Refer to Inspection Photos for observed compliance issues.

While on location no additional compliance issues were observed.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 307-380-7616

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment		
Corrective Action:	All equipment not hooked up or out of service will be removed from location.	Date:	11/15/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Double pipe rail		

Corrective Action:		Date:	
Type	PIT		
Comment:	Livestock wire on 1 pit. Livestock and barbed wire on 2nd pit.		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Horizontal Heated Separator	# 2		
Comment:	Unused equipment 1 outside unit, (glycol unit or separator in closed up shed)		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	w/ dehy in use		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead tree		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			

Inspected Facilities									
Facility ID:	112983	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	AC
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	223136	Type:	WELL	API Number:	081-06498	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	February 2025 Production Report								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: _____ Lined: NO Pit ID: 112983 Lat: 40.933583 Long: -108.346041

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Livestock Fencing Condition: _____

Comment:

Corrective Action

Date:

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date:

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date:

Type: _____ Lined: NO Pit ID: 489679 Lat: 40.933298 Long: -108.347031

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Livestock Fencing Condition: _____

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective
Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective
Action

Date:

Permit:	Facility ID	Permit Num	Expiration Date
	112983	403274095	
	112983	403274095	

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715501673	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7037897
715501675	FIRR, Insp. #715501301	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7037898