

# Inspection Photos

Location Name: QB ENERGY OPERATING LLC ALP 25-9C (J25NW) Pad

Location #: 335321




Photo # 9556 From Entrance to location

Photo # 9557 Location

## Inspection Photos

Location Name: QB ENERGY OPERATING LLC ALP 25-9C (J25NW) Pad

Location #: 335321



Photo # 9558 Location



Photo # 9559 Location

## Inspection Photos

Location Name: QB ENERGY OPERATING LLC ALP 25-9C (J25NW) Pad

Location #: 335321



Photo # 9560 Location



Photo # 9561 Location

## Inspection Photos

Location Name: QB ENERGY OPERATING LLC ALP 25-9C (J25NW) Pad

Location #: 335321



Photo # 9562 Location



Photo # 9563 Location

## Inspection Photos

Location Name: QB ENERGY OPERATING LLC ALP 25-9C (J25NW) Pad

Location #: 335321



**Photo # 9564 Hole in secondary containment liner/liner needs maintenance**



**Photo # 9565 Hole in secondary containment liner/liner needs maintenance**

## Inspection Photos

Location Name: QB ENERGY OPERATING LLC ALP 25-9C (J25NW) Pad

Location #: 335321



**Photo # 9566 Hole in secondary containment liner/liner needs maintenance**



**Photo # 9567 Hole in secondary containment liner/liner needs maintenance**

## Inspection Photos

Location Name: QB ENERGY OPERATING LLC ALP 25-9C (J25NW) Pad

Location #: 335321



Photo # 9568 Sign at entrance to location laying on the ground