

# Inspection Photos

05/6/2025

**Operator:** GUNNISON ENERGY LLC - 10515

**Location ID:** 334446

**Inspection Doc:** 718100505

Gunnison County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 334446



**Photo 1:** Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location from south, southwest, northwest to north. Photos examples showing interim reclamation to reduce the Location to areas only needed for production has not been performed in accordance with 1003 Rules and Form 4 Variance COAs.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 334446



**Photo 2:** See comments under photo 2.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 334446



**Photo 3:** Photos 3-4 taken from the north end of the Location. Photos provide an overview of the Location east, southeast, southwest to west. Photos examples showing interim reclamation to reduce the Location to areas only needed for production has not been performed in accordance with 1003 Rules and Form 4 Variance COAs.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 334446



**Photo 4:** See comments under photo 3



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 334446



**Photo 5:** Photo taken from the cut slopes on the west end of the Location. Photos show Noxious weed (Common Mullein) establishment on the Location. Common mullein is a biennial plant that produces a basal rosette in the first year of growth (Yellow arrow); the plant bolts with an erect stem during its second year of growth (Red Arrow). Weed management efforts to prevent Undesirable Plant Establishment have not occurred, or have been inadequate over the past few years.



## Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 334446



**Photo 6:** Photos 6-7 taken from the cut slopes on the west end of the Location. Photos examples showing plastic corrugated pipe/hose observed within the stormwater ditch; hose is in disrepair considered debris.



## Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 334446



**Photo 7:** See comments under photo 6.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources