

# Inspection Photos

Loc: 476137

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 5/13/2025

County: Cheyenne



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Drone aerial photo facing northeast toward the tank battery facility. There is a new spill that has recently occurred in addition to previous spills. The top of the tank shown at red arrow still has oily fluids that have not been cleaned up.





## Inspection Photos



**Photo 2.** Drone aerial photo facing northwest toward the tank battery. There is oily liquid shown on top of the tank at red arrow which need to be cleaned up and properly disposed. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 476137 | Date: 5/13/2025



## Inspection Photos



**Photo 3.** Drone aerial photo facing northwest toward the tank battery facility. There is a new spill that has recently occurred in addition to previous spills at this same area and at the same equipment.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc: 476137 | Date: 5/13/2025



## Inspection Photos



**Photo 4.** Drone aerial photo facing toward the heater treater where spill occurred.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc: 476137 | Date: 5/13/2025



## Inspection Photos



**Photo 5.** Drone aerial photo facing down toward the north side of the tank battery. Oil stained soils still remain around the tanks and have not been cleaned up.





## Inspection Photos



**Photo 6.** Drone aerial photo facing south toward the tank battery facility. E&P waste material remains on plastic liner at this area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc: 476137 | Date: 5/13/2025



## Inspection Photos



**Photo 7.** Facing southwest toward the tank battery. The E&P waste from the previously observed spill remains at the north side of the tank battery.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 476137 | Date: 5/13/2025



## Inspection Photos



**Photo 8.** Facing southeast toward the tank battery. The oil stained waste remains around the tanks. Some of the tanks were removed since the previous inspection.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 476137 | Date: 5/13/2025



## Inspection Photos



**Photo 9.** Facing southeast toward the area where new and additional spill recently occurred.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc: 476137 | Date: 5/13/2025



## Inspection Photos



**Photo 10.** Southeast corner of the location facing northwest toward the tank battery facility. There are signs of a leak at the top of the fiberglass tank shown at red arrow.





## Inspection Photos



**Photo 11.** Facing west toward the area where new and additional spill recently occurred.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc: 476137 | Date: 5/13/2025



## Inspection Photos



**Photo 12.** There is puddled oil free fluids shown at red arrow that needs immediate clean up.

