

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC COUEY 32-14 (N32) Pad

Location #: 334856



Photo # 315 From entrance to location




Photo # 316 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC COUEY 32-14 (N32) Pad

Location #: 334856



Photo # 317 Location



Photo # 318 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC COUEY 32-14 (N32) Pad

Location #: 334856



Photo # 319 Location



Photo # 320 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC COUEY 32-14 (N32) Pad

Location #: 334856



Photo # 321 Location



Photo # 322 Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC COUEY 32-14 (N32) Pad

Location #: 334856



Photo # 323 Weeds in secondary containment



Photo # 324 Weeds in secondary containment

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC COUEY 32-14 (N32) Pad

Location #: 334856



Photo # 325 Weeds in secondary containment



Photo # 326 Emergency contact # on wellhead signs incorrect/# is disconnected & not in service

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC COUEY 32-14 (N32) Pad
Location #: 334856



Photo # 327 Emergency contact # on signs at intersection of Mamm Creek Road & start of lease road incorrect/# is disconnected & not in service