

Inspection Photos
Location Name: Hazel McHale #2 Flowline
Spill ID: 489684



Excavation with Groundwater observed



Inspection Photos
Location Name: Hazel McHale #2 Flowline
Spill ID: 489684



Excavation fencing has fallen



Inspection Photos
Location Name: Hazel McHale #2 Flowline
Spill ID: 489684



Excavation photos. No benching or sloping.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Hazel McHale #2 Flowline
Spill ID: 489684



Excavation and fencing photos



Inspection Photos
Location Name: Hazel McHale #2 Flowline
Spill ID: 489684



Contaminated Stockpile



Contaminated soil is overflowing onto the ground past the liner



Inspection Photos
Location Name: Hazel McHale #2 Flowline
Spill ID: 489684



Contaminated Stockpile



Contaminated Stockpile



Inspection Photos
Location Name: Haezl McHale #2 Flowline
Spill ID: 489684



Contaminated soil is overflowing onto the ground past the liner



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Hazel McHale #2 Flowline
Spill ID: 489684



Stockpile soil has runoff to the ground beyond the liner



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Hazel McHale #2 Flowline
Spill ID: 489684



Contaminated stockpile



Liner issues



Inspection Photos
Location Name: Hazel McHale #2 Flowline
Spill ID: 489684



Inadequate trench to prevent stormwater runoff

