

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	PHOTO 4: PRODUCED WATER TANK BATTERY. NFPA, CAPACITY AND CONTENTS NOT LABELED ON TANK.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/19/2025

Emergency Contact Number:		
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 7: UNUSED EQUIPEMENT (UNUSED RISERS NOT MARKED OR LABELED INSIDE UNUSED SHED).		
Corrective Action:	MARK OR REMOVE UNUSED AND OR UNNESSESARY RISERS PER RULE 606. CA DATE 6/14/2025.	Date:	06/14/2025
Type	TRASH		
Comment:	PHOTO 8 - 12: TRASH AND OR DEBREE FROM DETERIORATING SHED ON AND AROUND LOCATION MOSTELY TO THE SOUTH AND SOUTHEAST OF SHED.		
Corrective Action:	INSPECT AND REMOVE ALL TRASH AND DEBREE FROM LOCATION AND SURROUNDING AREA PER RULE 606.	Date:	05/19/2025
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 6: UNUSED EQUIPMENT (SHED DOES NOT APPEAR TO BE IN USE OR USEFUL TO THE OPERATION OF THIS FACILITY, SHED IS DETERIORATING AND TRASH AND DEBREE FROM SHED IS ON AND AROUND LOCATION).		
Corrective Action:	REMOVE UNUSED EQUIPMENT PER RULE 606.	Date:	06/14/2025

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	# 2		
Comment:	PHOTO 5: BIRD PROTECTORES MISSING OR NOT INSTALLED ON TWO PIPES IN TOP OF TANK.		
Corrective Action:	INSTALL BIRD PROTECTORS.	Date:	05/19/2025
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		

Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 217336 Type: WELL API Number: 071-06112 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/26/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716300979	INSP. POTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7051991