

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2025

Submitted Date:

05/09/2025

Document Number:

719000030

**FIELD INSPECTION FORM**Loc ID 326677 Inspector Name: GARCIA, CHARLES On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

16 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	<a href="#">All Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262346	WELL	PR	10/01/2019	CBM	067-08677	FEDERAL 02-11 2	PR

**General Comment:**[Inspection Report Summary](#)[On 4-24-25 I Inspector Charles Garcia conducted an on-site inspection.](#)[Location: Federal 02-11-2](#)[Operator: Simcoe LLC](#)[API#: 067-08677](#)[County: LaPlata](#)[Wood debris observed on west side of disturbance from what appears to be original pad construction".](#)

**Location**Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Sign at entrance of location Contact		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	Contact # 970-247-6916 Emergency #911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	Mature dead sunflowers from last season observed on east side of location in vegetation area		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Cattle panels around separator		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	None		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Cattle panels around separator		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Located in separator building Lasta metercalibration 11-21-24		

Corrective Action:		Date:	
Type: Flow Line	# 4		
Comment:	1-4" flowline from wellhead to separator. 1-2" flowline from separator dump valve to offsite produced water gathering system. 1-2" flowline from separator blowdown to produced water tank.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Electrical panels		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 0		
Comment:	Dead men removed		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Well Head oil stain around well Head		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		,
Comment:	Partially buried 21 BBL tank				
Corrective Action:				Date:	

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	262346	Type:	WELL	API Number:	067-08677	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	07/09/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0		Fluid Type:					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 

Gravel and compaction pass for lease road and location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000032	Location Pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7056661">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7056661</a>