

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/15/2025

Submitted Date:

05/18/2025

Document Number:

719000071

**FIELD INSPECTION FORM**Loc ID 333848 Inspector Name: GARCIA, CHARLES On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
,		FarmingtonRegulatoryTechs@hilcorp.com	All Inspections 6/21/2022

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216430	WELL	PR	08/20/2001	CBM	067-08036	HAMILTON 1-6	PR
296239	WELL	PR	01/06/2009	CBM	067-09564	HAMILTON 2-6	PR

**General Comment:**

Inspection Report Summary  
On 5/15/25 I Inspector Charles Garcia  
conducted an on-site inspection.  
Location: HAMILTON #1-6, #2-6  
Operator: HILCORP ENERGY COMPANY  
1-6 API#: 067-08036  
2-6 API#: 067-09564  
County: LaPlata

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	LOCATION SIGNS AT WELL HEADS		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	505-324-5170 911 EMERGENCY	
Corrective Action:		Date:

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	GRAVEL SCRAPER ON SOUTH SIDE OD LOCATION SEE PICTURE #10		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	BARBWIRE		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Prime Mover	# 2		
Comment:	GAS		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	METER HOUSES LAST CALIBRATION #1-6 2/20/25 #2-6 2/20/25		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	PRIME MOVER OIL TANKS WITH SPILL PREVENTION		
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 7		
Comment:	2 DEAD MEN MARKERS ON GROUND		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	WELLHEADS		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	216430	Type:	WELL	API Number:	067-08036	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		06/12/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	296239	Type:	WELL	API Number:	067-09564	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		06/12/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		1		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000074	LOCATION PICTURES	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7056678">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7056678</a>