

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2025

Submitted Date:

05/12/2025

Document Number:

707801577

**FIELD INSPECTION FORM**Loc ID 439603 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10805

Name of Operator: FULCRUM ENERGY OPERATING LLC

Address: 240 SAINT PAUL STREET SUITE 502

City: DENVER State: CO Zip: 80206

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

15 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name   | Phone | Email                     | Comment |
|----------------|-------|---------------------------|---------|
| , Fulcrum      |       | inspections@fulcrumeo.com |         |
| Waldron, Emily |       | emily.waldron@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 444609      | WELL | PR     | 02/01/2025  | OW         | 057-06539 | Gregory 0780 1-9H   | PR          |
| 446904      | WELL | AP     | 07/01/2022  | LO         | 057-06568 | Mutual 0780 5-8H    | AP          |
| 446917      | WELL | AP     | 07/01/2022  | LO         | 057-06570 | Mutual 0780 6-8H    | AP          |
| 446918      | WELL | AP     | 07/01/2022  | LO         | 057-06571 | Mutual 0780 8-8H    | AP          |
| 446919      | WELL | AP     | 07/01/2022  | OW         | 057-06572 | Mutual 0780 7-8H    | AP          |
| 448055      | WELL | PR     | 08/17/2022  | OW         | 057-06586 | Castle 0780 6-17H20 | PR          |
| 448056      | WELL | PR     | 01/01/2024  | OW         | 057-06587 | Castle 0780 5-17H20 | PR          |
| 448057      | WELL | PR     | 04/01/2024  | OW         | 057-06588 | Castle 0780 8-17H20 | PR          |
| 448058      | WELL | PR     | 11/01/2023  | OW         | 057-06589 | Castle 0780 7-17H20 | PR          |
| 452319      | WELL | PR     | 06/01/2024  | OW         | 057-06603 | Janet 0780 1-16H21  | PR          |
| 452320      | WELL | PR     | 06/01/2024  | OW         | 057-06604 | Janet 0780 2-16H21  | PR          |
| 452321      | WELL | SI     | 01/01/2025  | OW         | 057-06605 | Janet 0780 4-16H21  | SI          |
| 452339      | WELL | PR     | 04/01/2024  | OW         | 057-06606 | Janet 0780 3-16H21  | PR          |

**General Comment:**

ECMC Inspection Report Summary

On Wednesday 5/7/2025, I, Inspector Scott Ramsey, conducted a follow up inspection at Gregory Pad, at Location # 439603 in Jackson county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed a tank battery. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Some random staining
2. No access or evidence of calibration cards.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location**Overall Good: ☐**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

## Emergency Contact Number:

Comment: 911/970-594-0477

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | OTHER   |       |            |
| Comment:           | Some random staining  |       |            |
| Corrective Action: | Remove stained material, dispose of properly and securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. | Date: | 06/20/2025 |
| Type               | OTHER   |       |            |
| Comment:           | Gas meter calibration record not legible or conspicuously displayed at meter.   |       |            |
| Corrective Action: | Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2)  | Date: | 06/23/2025 |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

|                           |                         |       |                 |
|---------------------------|-------------------------|-------|-----------------|
|                           |                         |       | corrective date |
| Type: Bradenhead          | # 9                     |       |                 |
| Comment:                  |                         |       |                 |
| Corrective Action:        |                         | Date: |                 |
| Type: Pump Jack           | # 9                     |       |                 |
| Comment:                  |                         |       |                 |
| Corrective Action:        |                         | Date: |                 |
| Type: Ancillary equipment | # 8                     |       |                 |
| Comment:                  | Crypto mining buildings |       |                 |
| Corrective Action:        |                         | Date: |                 |
| Type: Ancillary equipment | # 4                     |       |                 |
| Comment:                  | Gas powered generators  |       |                 |
| Corrective Action:        |                         | Date: |                 |

|                       |     |       |
|-----------------------|-----|-------|
| Type: Bird Protectors | # 4 |       |
| Comment:              |     |       |
| Corrective Action:    |     | Date: |

**Tanks and Berms:**

|                    |   |          |           |         |        |
|--------------------|---|----------|-----------|---------|--------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
| CONDENSATE         | 1 | 400 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

| Inspected Facilities   |            |                       |            |                  |
|--|------------|-----------------------|------------|------------------|
| Facility ID: 444609  | Type: WELL | API Number: 057-06539 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>  |            |                       |            |                  |
| Comment:   | Producing  |                       |            |                  |
| Corrective Action:   |            |                       |            | Date:            |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |            |                       |            |                  |
| Facility ID: 446904  | Type: WELL | API Number: 057-06568 | Status: AP | Insp. Status: AP |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |            |                       |            |                  |
| Facility ID: 446917  | Type: WELL | API Number: 057-06570 | Status: AP | Insp. Status: AP |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |            |                       |            |                  |
| Facility ID: 446918  | Type: WELL | API Number: 057-06571 | Status: AP | Insp. Status: AP |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |            |                       |            |                  |
| Facility ID: 446919  | Type: WELL | API Number: 057-06572 | Status: AP | Insp. Status: AP |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |            |                       |            |                  |
| Facility ID: 448055  | Type: WELL | API Number: 057-06586 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>  |            |                       |            |                  |
| Comment:   | Producing  |                       |            |                  |
| Corrective Action:   |            |                       |            | Date:            |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |            |                       |            |                  |
| Facility ID: 448056  | Type: WELL | API Number: 057-06587 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>  |            |                       |            |                  |
| Comment:   | Producing  |                       |            |                  |
| Corrective Action:   |            |                       |            | Date:            |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |            |                       |            |                  |
| Facility ID: 448057  | Type: WELL | API Number: 057-06588 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>  |            |                       |            |                  |
| Comment:   | Producing  |                       |            |                  |
| Corrective Action:   |            |                       |            | Date:            |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |            |                       |            |                  |
| Facility ID: 448058  | Type: WELL | API Number: 057-06589 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>  |            |                       |            |                  |
| Comment:   | Producing  |                       |            |                  |
| Corrective Action:   |            |                       |            | Date:            |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |            |                       |            |                  |
| Facility ID: 452319  | Type: WELL | API Number: 057-06603 | Status: PR | Insp. Status: PR |

|                    |           |       |  |
|--------------------|-----------|-------|--|
| Producing Well     |           |       |  |
| Comment:           | Producing |       |  |
| Corrective Action: |           | Date: |  |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 452320 | Type: | WELL | API Number: | 057-06604 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

|                    |           |       |  |
|--------------------|-----------|-------|--|
| Producing Well     |           |       |  |
| Comment:           | Producing |       |  |
| Corrective Action: |           | Date: |  |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 452321 | Type: | WELL | API Number: | 057-06605 | Status: | SI | Insp. Status: | SI |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

|                    |   |       |  |
|--------------------|---|-------|--|
| Idle Well          |   |       |  |
| Purpose:           | <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____ |       |  |
| Comment:           | Last produced 1/2025  |       |  |
| Corrective Action: |   | Date: |  |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 452339 | Type: | WELL | API Number: | 057-06606 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

|                    |           |       |  |
|--------------------|-----------|-------|--|
| Producing Well     |           |       |  |
| Comment:           | Producing |       |  |
| Corrective Action: |           | Date: |  |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Culverts                |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |
| Gravel           |                 |                         |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 404202344    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047444">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047444</a> |
| 707801581    | Photo log            | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047430">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047430</a> |