

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2025

Submitted Date:

05/13/2025

Document Number:

710500500

FIELD INSPECTION FORMLoc ID 386829 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Giena, Zeches		gzeches@ogrisop.com	
Baca, Dave		dbaca@ogrisop.com	
Serna, Abe		abe.serna@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301623	WELL	TA	08/01/2024	GW	071-09757	GOLDEN EAGLE 17-15H	EI

General Comment:

This is an Environmental Inspection for the Golden Eagle 17-15 H well location located in Las Animas County Colorado. Rem Project # 39697.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Well placard posted at wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐**Spills:**

Type	Area	Volume		
Other	WELLHEAD			
Comment:	At the time of inspection, a grey material was observed adjacent to the wellhead.			
Corrective Action:	Report spill or release of E&P waste or produced fluids in accordance with Rule 912.b. Contact ECMC EPS Staff Per Rule 912.b.			Date: <u>05/15/2025</u>

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	301623	Type:	WELL	API Number:	071-09757	Status:	TA	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental

Spill/Remediation:

Comment:

This is an Environmental Inspection for the Golden Eagle 17-15 H well location and Remediation Project # 39697. At the time of inspection, a grey material was observed adjacent to the wellhead.

In addition, Form 42 Document # 404149810 identified the on location flowline was to be removed on 5/06/2025. Operator shall provide photos taken at the time of wellhead cut and cap and flowline removal.

Operator shall continue quarterly reporting for Remediation Project # 39697 until the site is compliant with Table 915-1 standards.

Corrective Action:

Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404202696	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047909
710500501	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047891