

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404210971

Date Received:

05/20/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Dolezal, Pat

970-332-3585

pat.dolezal@ownresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 698603325

Inspection Date: 03/13/2025

FIR Submit Date: 03/20/2025

FIR Status: _____

Inspected Operator Information:

Company Name: OWN RESOURCES OPERATING LLC

Company Number: 10699

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

LOCATION - Location ID: 303547

Location Name: BROPHY, T-64N46W Number: 31SWNW County: YUMA

Qtrqtr: SWN Sec: 31 Twp: 4N Range: 46W Meridian: 6
W

Latitude: 40.274190 Longitude: -102.562820

FACILITY - API Number: 05-125- -00 Facility ID: 253268

Facility Name: BROPHY, T Number: 50-31

Qtrqtr: SWN Sec: 31 Twp: 4N Range: 46W Meridian: 6
W

Latitude: 40.274190 Longitude: -102.562820

CORRECTIVE ACTIONS:

1 CA# 203511

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 04/20/2025

Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil.

Response: CA COMPLETED

Date of Completion: 03/26/2025

Operator Comment: Check valve was replaced. Operator has photos but unable to attach

ECMC Decision: _____

ECMC
Representative:

2 CA# 203512

Corrective Action: Calibrate gas metering equipment annually to comply with rule 430.d.(1).

Date: 04/20/2025

Response: CA COMPLETED

Date of Completion: 04/08/2025

Operator
Comment:

Meter has been calibrated

ECMC Decision: _____

ECMC
Representative:

3 CA# 203513

Corrective Action: Operators will promptly investigate, and if appropriate, repair, replace, or remediate any malfunctioning equipment or process. Comply with Rule 609.a.

Date: 03/14/2025

15 days. If leak is found Immediate call to operator 24 hours to fix the leak or isolate leak.

Response: CA COMPLETED

Date of Completion: 03/26/2025

Operator
Comment:

Check valve was replaced. Operator has photos but unable to attach

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Pat Dolezal

Signed: _____

Title: Regulatory Specialist

Date: 5/20/2025 1:23:03 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404210971	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files